

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave.St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-021393**Date Inspected:** 06-Feb-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Lv Li Qing**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector Larry Viars was present during the times noted above for observations relative to the work being performed.

Bay 14-

This QA Inspector observed the following work in progress: Flux Cored Arc Welding (FCAW) of OBG Segment 13AE bearing seat weld, SEG3007AZ-063. ZPMC welder were identified as 055564. ZPMC CWI was identified as Lv Li Qing. The welding appeared to be in conformance with ZPMC welding produre specification WPS-B-T-2233-ESAB.

Flux Cored Arc Welding (FCAW) of OBG Segment 13AE bearing seat weld, SEG3007AZ-099. ZPMC welder were identified as 055491. ZPMC CWI was identified as Lv Li Qing. The welding appeared to be in conformance with ZPMC welding produre specification WPS-B-T-2233-ESAB.

Shielded Metal Arc Welding (SMAW) of OBG Segment 13AE edge beam to floor beam weld, SEG3007P-087. ZPMC welder were identified as 037743. ZPMC CWI was identified as Lv Li Qing. The welding appeared to be in conformance with ZPMC weld repair report WR 20183 and welding produre specification WPS-345-SMAW-3G(3F)-FCM-Repair.

Shielded Metal Arc Welding (SMAW) of OBG Segment 13AE edge beam to floor beam weld, SEG3007R-160. ZPMC welder were identified as 037723. ZPMC CWI was identified as Lv Li Qing. The welding appeared to be

---

## WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---

in conformance with ZPMC welding procedure specification WPS-345-SMAW-3G(3F)-FCM-Repair.

Shielded Metal Arc Welding (SMAW) of OBG Segment 13AE edge beam to floor beam weld, SEG3007R-151. ZPMC welder were identified as 037723. ZPMC CWI was identified as Lv Li Qing. The welding appeared to be in conformance with ZPMC weld repair report WR 20183 welding procedure specification WPS-345-SMAW-4G(4F)-FCM-Repair.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

### Summary of Conversations:

Only general conversation between QA and QC occurred this date.

### Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, 150 0042 2372, who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	Viars,Larry	Quality Assurance Inspector
<b>Reviewed By:</b>	McClendon,Timothy	QA Reviewer

---